

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.

No. 264

Date : 15/02/19

It is certified that an inspection team headed by RAKESH KUMAR RAHORA
S.D.O. PUBLIC HEALTH ENGINEERING SUB DN. MULTAI (Name of Officers
with designation) from PUBLIC HEALTH ENGINEERING DEPT. (Name of
Department/Office) inspected the WATER SAMPLE OF VASANT
INTERNATIONAL PUBLIC SCHOOL NH-69 THAVARIA. (Name & Address of
the School) on 11/02/19 and found that the HASPUR ROAD MULTAI
VASANT INTERNATIONAL
PUBLIC SCHOOL NH-69 THAVARIA HASPUR ROAD (Name of school) has safe
drinking water facilities for the students and members of staff of the institution and is maintaining
the hygienic sanitation condition in the school building & the campus as per the norms
prescribed by the Central/State/U.T Govt.

The above valid for a period of One year.

Signature with Seal : [Signature]

Name : (R. K. RAHORA)

Designation : Assistant Engineer
P.H.E. Sub Dn. Multai
M.P.

To
Principal

VASANT INTERNATIONAL PUBLIC
SCHOOL NH-69 THAVARIA HASPUR ROAD MULTAI

(Name & Address of the Institution)

No:.....

Date: 06.03.2019


HEALTH AND SANITARY CERTIFICATE
TO WHOM SO EVER IT MAY CONCERN

Name of the building : Vasant International Public School at NH-47, Nagpur Road,
Village- Thawriya, Post- Kamath, Tah.-Multai Dist.- Betul, M.P. 460661.

The above building was visited by me on 06-03-19 by DR. RAJNISH SHARMA
(Name of the Health Inspector). The school building has provided proper sanitary ^(B.M.O.) arrangements. In my opinion it is fit for the purpose of running school.


डॉ. राजनीश शर्मा
रजि. नंबर-6730
सामु. स्वास्थ्य केन्द्र
मुलताई, जि. बैतूल

B.M.O.
CHC MULTAI
DISTT. BETUL (M.P.)


B.M.O.
CHC MULTAI
DISTT. BETUL (M.P.)

06-03-19